

Figure S1. Ultrasound Guided Peripheral Catheter Insertion



Figure S2. Gel Clean-Up



Figure S3. Survey Question Gel Removal

In your personal experience, has inadequate ultrasound gel removal resulted in PIV securement/dressing adhesive failure?




Figure S4. Gel-Free Insertion Dressing

